

STEP 3



TIP SHEET

D•HAZE®

HAZE REMOVER

Screen Ghost and Haze Remover

Made with Soybeans • 100% Biodegradable • Non-Toxic and Non-Caustic

Franmar's Haze Remover is one of the safest and most effective ghost and haze removers in the industry today! Unlike traditional caustic haze removers, **Franmar's Haze Remover** will not damage screen mesh no matter how long you leave it on. Good haze removal practices save screen printers money, with longer usability of screens.

Directions

- 1 Spray or pour a minimal amount onto screen haze/ghost image.
- 2 Scrub both sides of screen with dedicated Biggee™ pad or nylon brush.
- 3 Rinse screen clean with pressured water.

Usage Tips

- Use each time immediately after removal of stencil removal or practice will not set in the screen.
- Control amount by using a squeegee. Holding frame close as Haze Remover will remove the glue holding the mesh to the frame.
- Use Franmar's Screen Degreaser to know your mesh.

Chat with a live customer service rep (No phone menu maze!)

800-538-5069

7am - 5:30pm Mon - Thurs. Friday 7am - 5:00pm CT

or visit our website: www.franmar.com

WARNING: This product can expose you to chemicals including n-methyl-2-pyrrolidone which is known to the State of California to cause birth defects or other reproductive harm. For more information, go to www.P65Warnings.ca.gov.



rev. 6/15/2015