

STEP 3

 Franmar

TIP SHEET

D•HAZE® GEL

HAZE REMOVER GEL

Screen Ghost and Haze Remover

Made with Soybeans • 100% Biodegradable • Non-Toxic and Non-Caustic

Franmar's Haze Remover Gel is an exclusive gel formula that allows greater control for removing ghost and haze images. This gel formula clings to the affected haze area and can be left on for long periods of time for tough or stubborn ghost images. Good haze removal practices save screen printers money, with longer usability of screens.

Directions

- 1 Pour a small amount on screen haze/ghost image.
- 2 Scrub both sides of screen with dedicated Biggee™ pad or nylon brush. Set aside and leave gel to work.
- 3 Rinse screen clean with pressured water.

Note: Do not let Haze Remover Gel sit on adhesive holding mesh onto frames.

Usage Tips

- Use each time immediately after production or stencil removal so that haze will not set in the screen.
- Great for removal of small areas of haze on old stencils.
- Use Franmar's Screen Degrasser to remove any residue.
- An hour or longer may be necessary for a few haze/ghost images, but Haze Remover Gel will not weaken or damage mesh.

Chat with a live customer service rep (No phone menu maze!)

800-538-5069

7am - 5:30pm Mon - Thurs. Friday 7am - 5:00pm CT

or visit our website: www.franmar.com

 Franmar®

rev. 6/15/2015